

## ATTACHMENT D - PRIOR ASBESTOS TEST REPORTS

### Aspen Hall (CASA)

1450 Madrone St. # "A"

Sample Location/ Room #	Test Date	Asbestos Containing Material	Quantity	Friable (Yes/No)	Condition	Asbestos Type/ %	Date Abated	Comments	Non- Asbestos Containing Material	Lab Sample #	Vendor
CASA-1H	8/15/2005	ND		n/a					Off white plaster aggregate	L145582-2	MACS Lab
CASA-2H	8/15/2006	ND		n/a					Off white ceiling material	L145582-3	MACS Lab
CASA-113-1	10/12/2004	ND		n/a					White plaster-1% Cellulose	L136050-6	MACS Lab
Mech Rm 008	1/30/1991	Pipe covering				7% Chrysotile				760015	Hall-Kimbrell
Mech Rm 008	1/30/1991	Pipe covering				10% Chrysotile				760016	Hall-Kimbrell
Mech Rm 008	1/30/1991	Pipe covering				T Chrysotile; 17% Amosite				760017	Hall-Kimbrell
Mech Rm 008	1/30/1991	ND		n/a	ND			MJP on pipe covering		760018	Hall-Kimbrell
Mech Rm 008	1/30/1991	MJP on pipe covering				2% Chrysotile; 8% Amosite				760019	Hall-Kimbrell
Mech Rm 008	1/30/1991	MJP on pipe covering				12% Chrysotile; 3% Amosite				760020	Hall-Kimbrell
Mech Rm 008	1/30/1991	Corrugated pipe covering				30% Chrysotile				760021/22/23	Hall-Kimbrell
Mech Rm 008	1/30/1991	MJP on corrugatd pipe c				2% Chrysotile; 6% Amosite				760024	Hall-Kimbrell
Mech Rm 008	1/30/1991	MJP on corrugatd pipe c				2% Chrysotile; 3% Amosite				760025	Hall-Kimbrell
Mech Rm 008	1/30/1991	MJP on corrugatd pipe c				2% Chrysotile; 8% Amosite				760026	Hall-Kimbrell
Mech Rm 008	1/30/1991	ND		n/a	ND			MJP on nonsuspect pipe cvr		760027/28/29	Hall-Kimbrell
Mech Rm 008	1/30/1991	Corrugated pipe covering				20% Chrysotile				760030/31/32	Hall-Kimbrell
Mech Rm 008	1/30/1991	MJP on corrugatd pipe c				2% Chrysotile; 2% Amosite				760033	Hall-Kimbrell
Mech Rm 008	1/30/1991	MJP on corrugatd pipe c				2% Chrysotile; 3% Amosite				760034	Hall-Kimbrell
Mech Rm 008	1/30/1991	MJP on corrugatd pipe c				2% Chrysotile; 4% Amosite				760035	Hall-Kimbrell
Mech Rm 008	1/30/1991	ND		n/a	ND			Wrappd cardbd/paper pipe		760036/37/38	Hall-Kimbrell
Mech Rm 008	1/30/1991	MJP on wrappd cardbd/paper				5% Chrysotile; 10% Amosite				760039	Hall-Kimbrell
Mech Rm 008	1/30/1991	MJP on wrappd cardbd/paper				5% Chrysotile; 7% Amosite				760040	Hall-Kimbrell
Mech Rm 008	1/30/1991	MJP on wrappd cardbd/paper				2% Chrysotile; 6% Amosite				760041	Hall-Kimbrell
Mech Rm 008	1/30/1991	ND		n/a	ND			MJP on nonsuspect pipe cvr		76042/43/44	Hall-Kimbrell
Mech Rm 008	1/30/1991	MJP on nonsuspect pipe cvr				10% Chrysotile				760045/47	Hall-Kimbrell
Mech Rm 008	1/30/1991	MJP on nonsuspect pipe cvr				8% Chrysotile				760046	Hall-Kimbrell
Rm 006A	1/30/1991	ND		n/a	ND			Wrappd cardbd/paper pipe		760048/49/50	Hall-Kimbrell
Rm 006A	1/30/1991	MJP on wrappd cardbd/paper				3% Chrysotile;3% Amosite				760051	Hall-Kimbrell
Rm 006A	1/30/1991	MJP on wrappd cardbd/paper				T Chrysotile; 2% Amosite				760052	Hall-Kimbrell
Rm 006A	1/30/1991	MJP on wrappd cardbd/paper				2% Chrysotile; 2% Amosite				760053	Hall-Kimbrell
Rm 101	1/30/1991	ND		n/a	ND			Sprayed acoustical plaster		760054	Hall-Kimbrell
Rm 104	1/30/1991	ND		n/a	ND			Sprayed acoustical plaster		760055	Hall-Kimbrell
Rm 116	1/30/1991	ND		n/a	ND			Sprayed acoustical plaster		760056	Hall-Kimbrell
Rm 207	1/30/1991	ND		n/a	ND			Sprayed acoustical plaster		760059	Hall-Kimbrell
Rm 206	1/30/1991	ND		n/a	ND			Sprayed acoustical plaster		760060	Hall-Kimbrell
Rm 210	1/30/1991	ND		n/a	ND			Sprayed acoustical plaster		760061	Hall-Kimbrell
Rm 202	1/30/1991	ND		n/a	ND			Sprayed acoustical plaster		760062	Hall-Kimbrell
Rm 204	1/30/1991	ND		n/a	ND			Sprayed acoustical plaster		760063	Hall-Kimbrell
Rm 309	1/30/1991	ND		n/a	ND			Sprayed acoustical plaster		760064	Hall-Kimbrell
Rm 310	1/30/1991	ND		n/a	ND			Sprayed acoustical plaster		760065	Hall-Kimbrell
Rm 311	1/30/1991	ND		n/a	ND			Sprayed acoustical plaster		760066	Hall-Kimbrell
Rm 303	1/30/1991	ND		n/a	ND			Sprayed acoustical plaster		760067	Hall-Kimbrell
Rm 304	1/30/1991	ND		n/a	ND			Sprayed acoustical plaster		760068	Hall-Kimbrell

**Baker Hall (CASB)**

1450 Madrone St. # "B"

Sample Location/ Room #	Test Date	Asbestos Containing Material	Quantity	Friable (Yes/No)	Condition	Asbestos Type/ %	Date Abated	Comments	Non- Asbestos Containing Material	Lab Sample #	Vendor
Rm 007	1/29/1991	ND		n/a		ND			Pipe covering	759362/363/364	Hall-Kimbrell
Rm 007	1/29/1991	MJP on pipe covering				2% Chrysotile; 5% Amosite				759365/367	Hall-Kimbrell
Rm 007	1/29/1991	MJP on pipe covering				3% Chrysotile; 4% Amosite				759366	Hall-Kimbrell
Rm 007	1/29/1991	Corrugated pipe covering				20% Chrysotile				759368/369/370	Hall-Kimbrell
Rm 007	1/29/1991	MJP on corrugatd pipe cvr				2% Chrysotile; 5% Amosite				759371	Hall-Kimbrell
Rm 007	1/29/1991	MJP on corrugatd pipe cvr				4% Chrysotile; T Amosite				759372	Hall-Kimbrell
Rm 007	1/29/1991	MJP on corrugatd pipe cvr				2% Chrysotile; 5% Amosite				759373	Hall-Kimbrell
Rm 003	1/29/1991	MJP on nonsuspect pipe cvr				4% Chrysotile; 16% Amosite				759374	Hall-Kimbrell
Rm 003	1/29/1991	MJP on nonsuspect pipe cvr				3% Chrysotile; 7% Amosite				759375	Hall-Kimbrell
Rm 003	1/29/1991	MJP on nonsuspect pipe cvr				2% Chrysotile; 8% Amosite				759376	Hall-Kimbrell
Rm 004	1/29/1991	Corrugated pipe covering				15% Chrysotile				759377	Hall-Kimbrell
Rm 004	1/29/1991	Corrugated pipe covering				20% Chrysotile				759378/379	Hall-Kimbrell
Rm 004	1/29/1991	MJP on corrugatd pipe cvr				3% Chrysotile; 4% Amosite				759380	Hall-Kimbrell
Rm 004	1/29/1991	MJP on corrugatd pipe cvr				2% Chrysotile; 5% Amosite				759381	Hall-Kimbrell
Rm 004	1/29/1991	MJP on corrugatd pipe cvr				2% Chrysotile; 8% Amosite				759382	Hall-Kimbrell
Rm 004	1/29/1991	ND		n/a		ND			Wrappd cardbd/paper pipe cvr	759383/384/385	Hall-Kimbrell
Rm 004	1/29/1991	MJP on wrappd cardbd/paper				2% Chrysotile; 8% Amosite				759386	Hall-Kimbrell
Rm 004	1/29/1991	MJP on wrappd cardbd/paper				4% Chrysotile; 13% Amosite				759387	Hall-Kimbrell
Rm 004	1/29/1991	MJP on wrappd cardbd/paper				T Chrysotile; 10% Amosite				759388	Hall-Kimbrell
Rm 002A	1/29/1991	ND		n/a		ND			Wrappd cardbd/paper pipe cvr	759389/390/391	Hall-Kimbrell
Rm 002A	1/29/1991	MJP on wrappd cardbd/paper				3% Chrysotile; 17% Amosite				759392	Hall-Kimbrell
Rm 002A	1/29/1991	MJP on wrappd cardbd/paper				3% Chrysotile; 12% Amosite				759393	Hall-Kimbrell
Rm 002A	1/29/1991	MJP on wrappd cardbd/paper				3% Chrysotile; 14% Amosite				759394	Hall-Kimbrell
Rm 002	1/29/1991	ND		n/a		ND			Drop or lay-in panel	759395/396/397	Hall-Kimbrell
Rm 002	1/29/1991	ND		n/a		ND			Acoustical tile	759400/401	Hall-Kimbrell
H002	1/29/1991	ND		n/a		ND			Acoustical tile	759402	Hall-Kimbrell
Rm 109	1/29/1991	ND		n/a		ND			Sprayd acoutical plaster	759403	Hall-Kimbrell
H101	1/29/1991	ND		n/a		ND			Sprayd acoutical plaster	759404	Hall-Kimbrell
Rm 113	1/29/1991	ND		n/a		ND			Sprayd acoutical plaster	759405	Hall-Kimbrell
Rm 202	1/29/1991	ND		n/a		ND			Sprayd acoutical plaster	759406	Hall-Kimbrell
Rm 207	1/29/1991	ND		n/a		ND			Sprayd acoutical plaster	759407	Hall-Kimbrell
Rm 211	1/29/1991	ND		n/a		ND			Sprayd acoutical plaster	759408	Hall-Kimbrell
H301	1/29/1991	ND		n/a		ND			Sprayd acoutical plaster	759409	Hall-Kimbrell
Rm 301	1/29/1991	ND		n/a		ND			Sprayd acoutical plaster	759410	Hall-Kimbrell
Rm 309	1/29/1991	ND		n/a		ND			Sprayd acoutical plaster	759411	Hall-Kimbrell
Rm 116	1/29/1991	ND		n/a		ND			Wrappd cardbd/paper pipe cvr	759412	Hall-Kimbrell
Rm 213	1/29/1991	Wrappd cardbd/paper pipe				T Chrysotile; T Amosite				759413	Hall-Kimbrell
Rm 313	1/29/1991	Wrappd cardbd/paper pipe				T Chrysotile				759414	Hall-Kimbrell
Rm 116	1/29/1991	MJP on wrappd cardbd/paper				5% Chrysotile;10% Amosite				759415	Hall-Kimbrell
Rm 213	1/29/1991	MJP on wrappd cardbd/paper				3% Chrysotile; 7% Amosite				759416	Hall-Kimbrell
Rm 213	1/29/1991	MJP on wrappd cardbd/paper				4% Chrysotile; 8% Amosite				759417	Hall-Kimbrell











**Hawthorne Hall (CASH)**

1450 Madrone St. # "H"

<u>Sample Location/ Room #</u>	<u>Test Date</u>	<u>Asbestos Containing Material</u>	<u>Quantity</u>	<u>Friable (Yes/No)</u>	<u>Condition</u>	<u>Asbestos Type/ %</u>	<u>Date Abated</u>	<u>Comments</u>	<u>Non- Asbestos Containing Material</u>	<u>Lab Sample #</u>	<u>Vendor</u>
Mech Rm 012H	2/5/1991	MJP on nonsupect pipe cover				3% Chrysotile				760280/282	Hall-Kimbrell
Mech Rm 012H	2/5/1991	MJP on nonsupect pipe cover				5% Chrysotile				760281/283/284/285	Hall-Kimbrell
Rm 35	2/5/1991	ND		n/a	ND				Acoustical tile	760286	Hall-Kimbrell
Rm 20	2/5/1991	ND		n/a	ND				Acoustical tile	760287/288	Hall-Kimbrell
H13	2/5/1991	ND		n/a	ND				Trowelled acoustical plaster	760289	Hall-Kimbrell
H12	2/5/1991	ND		n/a	ND				Trowelled acoustical plaster	760290	Hall-Kimbrell
H10	2/5/1991	ND		n/a	ND				Trowelled acoustical plaster	760291	Hall-Kimbrell
Rm 34	2/5/1991	ND		n/a	ND				Drop or lay-in panel	760292/293/294	Hall-Kimbrell
Rm 12D	2/5/1991	ND		n/a	ND				Acoustical tile	760295	Hall-Kimbrell
Rm 11	2/5/1991	ND		n/a	ND				Acoustical tile	760296	Hall-Kimbrell
Stairwell	2/5/1991	ND		n/a	ND				Acoustical tile	760297	Hall-Kimbrell
Rm 28	2/5/1991	ND		n/a	ND				Sprayed acoustical tile	760400	Hall-Kimbrell
Rm 13	2/5/1991	ND		n/a	ND				Sprayed acoustical tile	760401	Hall-Kimbrell
Rm 30	2/5/1991	ND		n/a	ND				Sprayed acoustical tile	760402	Hall-Kimbrell
Rm 32	2/5/1991	ND		n/a	ND				Sprayed acoustical tile	760403	Hall-Kimbrell
Rm 33	2/5/1991	ND		n/a	ND				Sprayed acoustical tile	760404	Hall-Kimbrell
H101	2/5/1991	ND		n/a	ND				Trowelled acoustical plaster	760405	Hall-Kimbrell
H100	2/5/1991	ND		n/a	ND				Trowelled acoustical plaster	760406	Hall-Kimbrell
Rm 108	2/5/1991	ND		n/a	ND				Trowelled acoustical plaster	760407	Hall-Kimbrell
Rm 101	2/5/1991	ND		n/a	ND				Sprayed acoustical tile	760408	Hall-Kimbrell
Rm 104	2/5/1991	ND		n/a	ND				Sprayed acoustical tile	760409	Hall-Kimbrell
Rm 107	2/5/1991	ND		n/a	ND				Sprayed acoustical tile	760410	Hall-Kimbrell
Rm 111	2/5/1991	ND		n/a	ND				Sprayed acoustical tile	760411	Hall-Kimbrell
Rm 113	2/5/1991	ND		n/a	ND				Sprayed acoustical tile	760412	Hall-Kimbrell
Rm 100	2/5/1991	ND		n/a	ND				Acoustical tile	760413/414/415	Hall-Kimbrell
Rm 119	2/5/1991	MJP on nonsupect pipe cover				5% Chrysotile				760416/417/418	Hall-Kimbrell
Rm 219	2/5/1991	MJP on nonsupect pipe cover				5% Chrysotile				760419/420/421	Hall-Kimbrell
Stairwell	2/5/1991	ND		n/a	ND				Trowelled acoustical plaster	760422	Hall-Kimbrell
H200	2/5/1991	ND		n/a	ND				Trowelled acoustical plaster	760423	Hall-Kimbrell
Rm 208	2/5/1991	ND		n/a	ND				Trowelled acoustical plaster	760424	Hall-Kimbrell
Rm 200	2/5/1991	ND		n/a	ND				Acoustical tile	760425/426/427	Hall-Kimbrell
Rm 203	2/5/1991	ND		n/a	ND				Sprayed acoustical tile	760428	Hall-Kimbrell
Rm 205	2/5/1991	ND		n/a	ND				Sprayed acoustical tile	760429	Hall-Kimbrell
Rm 207	2/5/1991	ND		n/a	ND				Sprayed acoustical tile	760430	Hall-Kimbrell
Rm 211	2/5/1991	ND		n/a	ND				Sprayed acoustical tile	760431	Hall-Kimbrell
Rm 214	2/5/1991	ND		n/a	ND				Sprayed acoustical tile	760432	Hall-Kimbrell
Stairwell	2/5/1991	ND		n/a	ND				Trowelled acoustical plaster	760433	Hall-Kimbrell
H301	2/5/1991	ND		n/a	ND				Trowelled acoustical plaster	760434	Hall-Kimbrell
Rm 308	2/5/1991	ND		n/a	ND				Trowelled acoustical plaster	760435	Hall-Kimbrell
Rm 302	2/5/1991	ND		n/a	ND				Sprayed acoustical tile	760436	Hall-Kimbrell
Rm 305	2/5/1991	ND		n/a	ND				Sprayed acoustical tile	760437	Hall-Kimbrell
Rm 309	2/5/1991	ND		n/a	ND				Sprayed acoustical tile	760438	Hall-Kimbrell
Rm 311	2/5/1991	ND		n/a	ND				Sprayed acoustical tile	760439	Hall-Kimbrell
Rm 314	2/5/1991	ND		n/a	ND				Sprayed acoustical tile	760440	Hall-Kimbrell





**Cascade Food Court (Including Kitchen)**

1450 Madrone St.

Sample Location/ Room #	Test Date	Asbestos Containing Material	Quantity	Friable (Yes/No)	Condition	Material Type/ %	Date Abated	Comments	Non- Asbestos Containing Material	Lab Sample #	Vendor
Mech Rm 4	2/6/1991	Pipe covering				5% Chrysotile				760464/465/466	Hall-Kimbrell
Mech Rm 4	2/6/1991	MJP on pipe covering				75% Chrysotile				760467/468/469	Hall-Kimbrell
Mech Rm 4	2/6/1991	MJP on nonsuspect piper cvr				5% Chrysotile				760470/471/472	Hall-Kimbrell
Mech Rm 4	2/6/1991	MJP on nonsuspect piper cvr				10% Chrysotile				760473/474/475	Hall-Kimbrell
Mech Rm 4	2/6/1991	Pipe covering				5% Chrysotile				760476/760477	Hall-Kimbrell
Mech Rm 4	2/6/1991	Pipe covering				5% Chrysotile; 5% Amosite				760478	Hall-Kimbrell
Mech Rm 4	2/6/1991	MJP on pipe covering				75% Chrysotile				760479	Hall-Kimbrell
Mech Rm 4	2/6/1991	ND		n/a		ND		MJP on pipe covering		760480/760481	Hall-Kimbrell
Mech Rm 4	2/6/1991	MJP on nonsuspect piper cvr				5% Chrysotile				760488/489/490	Hall-Kimbrell
Mech Rm 4	2/6/1991	MJP on nonsuspect piper cvr				5% Chrysotile				760491/492/493	Hall-Kimbrell
Mech Rm 4	2/6/1991	Boiler/tank insulation				10% Chrysotile; 15% Amosite				760494	Hall-Kimbrell
Mech Rm 4	2/6/1991	Boiler/tank insulation				15% Chrysotile; 15% Amosite				760495/496	Hall-Kimbrell
Tank 2-Mech Rm 4	2/6/1991	Boiler/tank insulation				5% Chrysotile				760497	Hall-Kimbrell
Tank 2-Mech Rm 4	2/6/1991	Boiler/tank insulation				20% Amosite				760498/499	Hall-Kimbrell
Tank 3-Mech Rm 4	2/6/1991	Boiler/tank insulation				5% Chrysotile; 5% Amosite				760300	Hall-Kimbrell
Tank 3-Mech Rm 4	2/6/1991	Boiler/tank insulation				15% Amosite				760301	Hall-Kimbrell
Tank 3-Mech Rm 4	2/6/1991	Boiler/tank insulation				10% Amosite				760302	Hall-Kimbrell
Tank 4-Mech Rm 4	2/6/1991	Boiler/tank insulation				15% Chrysotile; 10% Amosite				760304	Hall-Kimbrell
Tank 4-Mech Rm 4	2/6/1991	Boiler/tank insulation				20% Chrysotile; 15% Amosite				760305/306	Hall-Kimbrell
Tank 5-Mech Rm 4	2/6/1991	Boiler/tank insulation				5% Chrysotile; 20% Amosite				760307/309	Hall-Kimbrell
Tank 5-Mech Rm 4	2/6/1991	Boiler/tank insulation				15% Amosite				760308	Hall-Kimbrell
Tank 6-Mech Rm 4	2/6/1991	Boiler/tank insulation				20% Amosite				760310	Hall-Kimbrell
Tank 6-Mech Rm 4	2/6/1991	Boiler/tank insulation				10% Chrysotile; 10% Amosite				760311	Hall-Kimbrell
Tank 6-Mech Rm 4	2/6/1991	Boiler/tank insulation				10% Chrysotile; 5% Amosite				760312	Hall-Kimbrell
Tank 7-Mech Rm 4	2/6/1991	Boiler/tank insulation				5% Chrysotile; 10% Amosite				760313	Hall-Kimbrell
Tank 7-Mech Rm 4	2/6/1991	Boiler/tank insulation				2% Chrysotile; 10% Amosite				760314	Hall-Kimbrell
Tank 7-Mech Rm 4	2/6/1991	Boiler/tank insulation				20% Chrysotile; 10% Amosite				760315	Hall-Kimbrell
Tank 8-Mech Rm 4	2/6/1991	ND		n/a		ND		Boiler/tank insulation		760316	Hall-Kimbrell
Tank 8-Mech Rm 4	2/6/1991	Boiler/tank insulation				T Chrysotile				760317	Hall-Kimbrell
Tank 8-Mech Rm 4	2/6/1991	Boiler/tank insulation				2% Chrysotile				760318	Hall-Kimbrell
Tank 9-Mech Rm 4	2/6/1991	Boiler/tank insulation				5% Chrysotile; 10% Amosite				760319	Hall-Kimbrell
Tank 9-Mech Rm 4	2/6/1991	Boiler/tank insulation				10% Chrysotile; 5% Amosite				760320	Hall-Kimbrell
Tank 9-Mech Rm 4	2/6/1991	Boiler/tank insulation				10% Chrysotile; 5% Amosite				760321	Hall-Kimbrell
Tank 10-Mech Rm 4	2/6/1991	Boiler/tank insulation				10% Chrysotile; 2% Amosite				760322/760324	Hall-Kimbrell
Tank 10-Mech Rm 4	2/6/1991	Boiler/tank insulation				10% Chrysotile; 5% Amosite				760323	Hall-Kimbrell
Tank 1-Rm 003	2/6/1991	Boiler/tank insulation				5% Chrysotile; 10% Amosite				760325	Hall-Kimbrell
Tank 1-Rm 003	2/6/1991	Boiler/tank insulation				2% Chrysotile; 10% Amosite				760326	Hall-Kimbrell
Tank 1-Rm 003	2/6/1991	Boiler/tank insulation				10% Chrysotile; 10% Amosite				760327	Hall-Kimbrell
Tank 2-Rm 003	2/6/1991	Boiler/tank insulation				15% Amosite; 2% Crocidolite				760328/329	Hall-Kimbrell
Tank 2-Rm 003	2/6/1991	Boiler/tank insulation				2% Chrysotile; 15% Amosite; 2% Crocidolite				760330	Hall-Kimbrell
Tank 3-Rm 003	2/6/1991	Boiler/tank insulation				5% Amosite				760331	Hall-Kimbrell
Tank 3-Rm 003	2/6/1991	Boiler/tank insulation				5% Chrysotile; 10% Amosite				760332	Hall-Kimbrell
Tank 3-Rm 003	2/6/1991	Boiler/tank insulation				10% Chrysotile				760333	Hall-Kimbrell
H105	2/6/1991	ND		n/a		ND		Acoustical tile		760334	Hall-Kimbrell
Rm 115	2/6/1991	ND		n/a		ND		Acoustical tile		760335	Hall-Kimbrell
Rm 119	2/6/1991	ND		n/a		ND		Acoustical tile		760336	Hall-Kimbrell
Rm 120	2/6/1991	ND		n/a		ND		Acoustical tile		760337	Hall-Kimbrell
Rm 127	2/6/1991	ND		n/a		ND		Acoustical tile		760338	Hall-Kimbrell
Rm 127A	2/6/1991	ND		n/a		ND		Acoustical tile		760339	Hall-Kimbrell
Rm 129	2/6/1991	ND		n/a		ND		Drop or lay-in panel		760340/341/342	Hall-Kimbrell
Rm 106	2/6/1991	ND		n/a		ND		Acoustical tile		760343/344/345	Hall-Kimbrell
Rm 107	2/6/1991	ND		n/a		ND		Acoustical tile		760346/760347	Hall-Kimbrell
Rm 113	2/6/1991	ND		n/a		ND		Sprayed acoustical plaster		760348/349/350	Hall-Kimbrell
Mech Rm 200	2/6/1991	MJP on nonsuspect piper cvr				10% Chrysotile				760351/760353	Hall-Kimbrell
Mech Rm 200	2/6/1991	MJP on nonsuspect piper cvr				15% Chrysotile				760352	Hall-Kimbrell
Mech Rm 200	2/6/1991	MJP on nonsuspect piper cvr				10% Chrysotile				760354/355/356	Hall-Kimbrell

Attic-Rm 200	2/6/1991	ND		n/a		ND			Exterior duct insulation	760358/359	Hall-Kimbrell
Mech Rm 200	2/6/1991	ND		n/a		ND			Exterior duct insulation	760357	Hall-Kimbrell
Tank 5-Mech Rm 4	2/6/1991	ND		n/a		ND			Debris	760360/361/362	Hall-Kimbrell
	2/6/1991										
	2/6/1991										
	2/6/1991										
	2/6/1991										
food storage RM off 3/11/09		ND	door	no	poor	10%glass/60%minerial Agg./30% binder	eplaced3/09			09A062	Coleman Creek